Packing list for 35kV Inner cone plug-in termination (Single- core)					
No.	Description	Picture	Specification	QTY	Remarks
1	35kV Cable adaptor		1#/2#/3#	1 pcs	
2	Contacting ring		1#/2#/3#	1 pcs	
3	Pressure ring		1#/2#/3#	1 pcs	
4	Metal sheath			1 pcs	include: Seal ring,Compression spring,Adjust circle,Induction ring
5	Hex bolt		M12×16mm	3 pcs	
6	Hex bolt		M8×50mm	3 pcs	
7	Protecting jacket			1 pcs	
8	Tinned copper braid		25MM ² *1M	1 pcs	
9	Constant force spring			1 pcs	
10	Installation tape		J-10	1 roll	
11	Black PVC tape	0		1 roll	
12	phase tape		Yellow, red, green	1 pcs	
13	Abrasive paper			1 pcs	
14	Silicone lubricant	mer.	46g	1 pcs	
15	Dielectric cleaning tissue	Warfard To the second		3 pcs	
16	One-off PE gloves			1 pair	
17	White working gloves			1 pair	
18	Installation instruction	TABLE PROJECT STORM A STATE OF THE STATE OF		1 Sheet	
19	Certificate of Conformity	 I in the country I implies the country of the country of the country of the country If the Country of the country of		1 Sheet	package
20	Out-factory test record			1 Sheet	together
21	Packing list	 I we come the samp less the entry size is an interest requirement of the same entry and the same 		1 Sheet	